

Inspection Report

Inhi Customer

Property Address:

123 N Anystreet Any Town ID 99999



Inland Northwest Home Inspection LLC

Chip Kenny WA State License 746 P.O.Box 703 Lewiston Idaho 83501 208.791.5933

Table of Contents

<u>Cover Page</u>	<u> </u>
Table of Contents	2
Intro Page	3
1 Grounds	4
2 Exterior	8
3 Roof System (Exterior)	18
4 Kitchen Components and Appliances	23
5 Laundry Room/ Area/ Closet	27
6(A) Master Bath	29
6(B) Top Floor 3/4 Bath	32
6(C) Main Floor Full Bath	35
6(D) 1/2 Bath	37
7 Rooms	41
8 Interior Components	43
9 Attic/ Roof System (Interior)	47
10 Crawlspace	50
11 Plumbing System	54
12 Electrical System	60
13 Heating System(s)	64
14 A/C System(s)	66
SUMMARY 1 (Items of Concern and Potentia Safety Issues)	
SUMMARY 2 (Maintenance/ Monitor Items/ Deferred Cost Items)	96
Invoice	105

123 N Anystreet Page 2 of 105

Inland Northwest Home Inspection LLC

Customer

Date: 8/3/2018	Time: 02:00 PM	Report ID: Sample Report 1
Property: 123 N Anystreet Any Town ID 99999	Customer: Inhi Customer	Real Estate Professional:

All comments by the inspector should be considered before purchasing this home. Any recommendations by the inspector to repair or replace suggests a second opinion or further inspection by a qualified contractor. All costs associated with further inspection fees and repair or replacement of item, component or unit should be considered before you purchase the property.

Inspected (IN) = The item, component or unit was visually observed and if no other comments were made then it appeared to be functioning as intended allowing for normal wear and tear.

Not Inspected (NI)= This item, component or unit was not inspected and no determination is made as to whether or not it was functioning as intended. A reason will be stated as to why it was not inspected.

Not Present (NP) = This item, component or unit is not in this home or building.

<u>Limited Visibility (LV)</u> = The item, component or unit is either not visible or visibility is limited to the extent that an adequate determination cannot be made as to its condition or performance.

Item of Concern (IC) = The item, component or unit is not functioning as intended or is a potential safety concern. Further inspection by a qualified contractor or repairman is recommended. Items, components or units that can be repaired to satisfactory condition may not need replacement.

<u>Maintenance</u>/ <u>Monitoring Recommended (MM)</u> = The item, component or unit is showing typical age related evidence that repairs or maintenance are /may be needed in the future. An occasional visual examination is recommended and maintenance performed as needed

<u>Deferred Cost Item (DF)</u> = Item, system or component is nearing the end or exceeded its typical lifespan according to industry standards. Repair or replacement may be needed within the next 5 years

In Attendance:Type of building:Style of Home:Cutomer attending review at endSingle Family, Wood Frame2 Story, Crawlspace

State of Occupancy: Approximate age of building: Home Faces:

Occupied by Owner, Partially Furnished 100-125 Years East

Temperature (At start of Weather: Ground/Soil surface condition:

inspection): Clear Dry

Over 85 (F)

Rain/Snow in last 3 days:

No

1. Grounds

The Inspection of the site includes the building perimeter, land grade and water drainage directly adjacent to the foundation; trees and vegetation that directly adversely affect the structure, walks, grade steps. driveways, patios, and retaining walls contiguous with the structure. **The inspector will Describe** the material used for the driveways, walkways, patios, flatwork and retaining walls contiguous with the structure. **The inspector will Inspect:** (a) for serviceability of the driveways, steps, walkways, patios, flatwork and retaining walls contiguous with the structure (b) for proper grade and drainage slope (c) vegetation in close proximity of the home. **The inspector will Describe** any deficiencies of these systems or components. **The inspector is Not required to: Inspect** fences, privacy walls or retaining walls that are not contiguous with the structure. Report the condition of soil, trees, shrubs or vegetation unless they adversely affect the structure. **Evaluate** hydrological or geological conditions. Determine the adequacy of bulkheads, seawalls, breakwalls and docks

Styles & Materials

Driveway: Sidewalks and walkways: Steps/ Stoops/ Ramps/ Railings:

Gravel Concrete Wood

Brick/ Block/ Stone

Patios: Porches/Decks/ Balconies/Railings: Hose Bibs/ Hydrants:

Concrete Patio Wood Deck Domestic Water
Brick & Sand Patio Masonry/Concrete Piers

Wood Columns Wood Beams

Retaining Walls:

Railroad Ties

Items

1.0 Sidewalks/ Service Walks

Item of Concern

The sidewalk on the back of the house has settled creating a negative grade towards the house. This is allowing water to flow towards house and entering the crawlspace. Recommend further evaluation by licensed contractor to correct grade and proceed as recommended.



1.1 Steps/ Stoops/ Ramps and Applicable Railings

Item of Concern


(1) The wood steps to the front door show signs of wood rot and deterioration, as well as loose planking. This is creating a potential safety hazard. Recommend rebuilding steps for safety purposes.



(2) Back steps to upper deck are failing and are a safety hazard. Recommend rebuilding steps properly prior to use.



123 N Anystreet Page 5 of 105



1.2 Patios and Applicable Railings

Inspected, Item of Concern

Deteriorating brick and sand patios creating multiple trip hazards. Recommend repair as needed.



1.3 Decks, Porches, Balconies and Applicable Railings

Item of Concern

123 N Anystreet Page 6 of 105

Both upper and lower decks are not properly attached to the house. Deck ledgers should be attached with 1/2 lag bolts on 2 ft centers. Further evaluation for needed repairs by a licensed contractor is recommended.



1.4 Deck, Patio, Porch Covers

Inspected

1.5 Landscaping: Vegetation, Grading & Drainage Affecting Foundation and Building Inspected

1.6 Foundation Vent/ Basement Window Wells

Not Present

1.7 Water faucets (Hose bibs & Hydrants Attached to the house)

Inspected

1.8 Retaining Walls

Inspected

1.9 Evidence of underground fuel storage tank

Not Present, Limited Visibility

The grounds of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 7 of 105

2. Exterior

The Inspection of the site includes the building perimeter, land grade and water drainage directly adjacent to the foundation; trees and vegetation that directly adversely affect the structure, walks, grade steps. driveways, patios, and retaining walls contiguous with the structure. **The inspector will Describe** the material used for the driveways, walkways, patios, flatwork and retaining walls contiguous with the structure. **The inspector will Inspect:** (a) for serviceability of the driveways, steps, walkways, patios, flatwork and retaining walls contiguous with the structure (b) for proper grade and drainage slope (c) vegetation in close proximity of the home. **The inspector will Describe** any deficiencies of these systems or components. **The inspector is Not required to: Inspect** fences, privacy walls or retaining walls that are not contiguous with the structure. Report the condition of soil, trees, shrubs or vegetation unless they adversely affect the structure. **Evaluate** hydrological or geological conditions. Determine the adequacy of bulkheads, seawalls, breakwalls and docks

Styles & Materials

Gutters/ Scuppers/Evestrough:

Metal

Trim/ Soffit/ Fascia/ Flashing:

Wood

Wood Composite

Metal

Foundation Wall Material:

Poured Concrete Concrete Block **Siding Style:**

Lap

Wood shakes

Exterior Entry Doors:

Steel door with Window Wood Door with Window

Siding Material:

Composite board

Windows:

Wood

Metal Vinyl

Items

2.0 Roof Drainage Systems (Gutters/Downspouts)

Item of Concern

Recommend installing gutters with proper downspouts around the entire house in order to prevent unwanted moisture from entering crawlspace.




2.1 Siding

Inspected, Maintenance/ Montitoring Recommended

Inland Northwest Home Inspection LLC

Customer

The siding is an overall satisfactory condition with typical maintenance and minor repairs required. Recommend repair as needed, prep and paint/ stain in order to prevent deterioration of the siding. This type of siding is very susceptible to moisture penetration if not properly maintained.



123 N Anystreet Page 9 of 105







2.2 Soffit/ Fascia/ FlashingInspected, Maintenance/ Montitoring Recommended

123 N Anystreet Page 10 of 105

Multiple areas of damaged soffit and fascia. Recommend repair as needed, prep and paint..








2.3 Vent outlets through wall and soffit (Bathroom, Kitchen & Dryer Exhaust Vents) Inspected

2.4 Window, Door & Corner Trim Inspected

123 N Anystreet Page 11 of 105

Areas of door, window and / or corner trim that shows signs of wood rot and deterioration due to lack of maintenance. Recommend repairing trim as needed, prep and paint to prevent further deterioration.





2.5 Exterior Doors (Hinges, Hardware, Weatherstripping)
Inspected, Item of Concern

123 N Anystreet Page 12 of 105

Inland Northwest Home Inspection LLC

The glass is broken out of the back door. Recommend repair for safety purposes.



2.6 Windows
Inspected

2.7 Caulking

Item of Concern

123 N Anystreet Page 13 of 105

Caulking should be checked annually and renewed as needed.

All joints, seams, edges and penetrations should be caulked to prevent moisture penetration resulting in damage and deterioration



123 N Anystreet Page 14 of 105



2.8 Foundation wall / Slab (visible portion only) Inspected

2.9 Switches and Light fixtures Inspected


2.10 Exterior Outlets (Correct polarity & Grounding -GFI protected- Weatherproof covers)

Item of Concern

123 N Anystreet Page 15 of 105

(1) All exterior outlets should be GFI protected for safety purposes. Recommend installing GFI protection for exterior outlets. (Either GFI outlets or breaker)






GFI Breaker/ outlet

123 N Anystreet Page 16 of 105

(2) All electrical wiring should be installed in a junction box of proper cover for safety purposes.



The grounds of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 17 of 105

3. Roof System (Exterior)

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

Styles & Materials

Roof-Type:

French Hip Gable

Roof Covering:

Architectural

Approximate Rated Lifespan of Roof as per Manufacturer:

Architechtural Shingle 35-50 years

Chimney (visible from roof):

Chimney Chase Masonry- Brick/Block/Stone/Cultured Product/Stucco/ EIFS Chimney Flue/ Liner Unlined

Roof Pitch:

Medium Slope -3:12- 5:12 Pitch Steep Slope > 5:12 Pitch

Layers of roofing:

1+ Layers

Conditions other than typical aging:

Alligatoring Blistering Cracking

Excessive Granule Loss

Ventilation (Visual from Exterior):

Passive Roof Vents

Viewed roof covering from: Walked roof

Approximate age of roofing:

21-25 Years

Valley Material:

Metal

Items

3.0 Roof Coverings

Inspected, Item of Concern, Maintenance / Monitor Recommended, Deffered cost item

(1) Improperly lapped shingles on roof. Recommend further evaluation by license roofer for all needed repairs.




123 N Anystreet Page 18 of 105

(2) Cleaning moss from the roof is recommended in order to extend the lifespan of the covering, DO NOT PRESSURE WASH as this will damage the shingles. Use a rough surface push broom for best results.



(3) Broken and missing shingles, excessive granule loss and cracking are all indications that the roof is nearing the end of its typical lifespan. Repairs may be needed within the next 5 years.



123 N Anystreet Page 19 of 105





3.1 Flashings (Roof Edge & Wall & Counter Flashing)

Item of Concern

The drip edge is separating from the fascia in multiple sections of the roof. The drip edge prevents water from wicking up the sheathing creating wood rot and possible mold related issues. Recommend further evaluation by a licensed roofer for all needed repairs and proceed as recommended



3.2 Valleys, Ridges & Hips

Inspected

123 N Anystreet Page 20 of 105

3.3 Plumbing Vent Flashings

Item of Concern

Two plumbing vent flashing Have failed and require replacing. Recommend repair by a qualified professional





3.4 Chimney(s) (Viewed from roof) Inspected

3.5 Class B Vents (Stove Pipes) / Furnace Exhaust Vents (PVC) & Flashings Item of Concern

123 N Anystreet Page 21 of 105

Rain cap /spark arrestor is missing from stove pipe. Recommend repair for safety purposes.



3.6 Bathroom and Kitchen exhaust fans (Visual verfication of Venting)

Not Present

3.7 Ventilation of Roof (Exterior view)

Inspected

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 22 of 105

4. Kitchen Components and Appliances

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

Styles & Materials

Exhaust/Range hood/ Ceiling Exhaust: Sheet Linoleum/ Vinyl

Re-circulating Wood

Countertop: Backsplash:

Tile/ Ceramic, Porcelain, Glass Laminate

Icemaker: Installed **Functional**

Cabinetry:

Items

4.0 Ceiling

Inspected

4.1 Walls

Inspected

4.2 Floors

Inspected

4.3 Windows

Inspected

4.4 Heat/ Cooling Source

Inspected

4.5 Counters and Cabinets (representative number)

Inspected

4.6 Caulking

Inspected

4.7 Plumbing Drain, Waste and Vent Systems

Inspected

4.8 Plumbing Water Supply, Distribution System and Fixtures

Inspected

4.9 Dishwasher

Not Inspected, Item of Concern

The dishwasher did not operate at the time of the inspection. No determination is made.




4.10 Dishwasher drain lineMaintenance / Monitor Recommended

123 N Anystreet Page 24 of 105

Dishwasher drain line should either be looped at the high point in cabinet or have an air gap installed to prevent backflow from the sink to the dishwasher.





Dishwasher drain line

4.11 Food Waste Disposer

Item of Concern

The garbage disposal was sitting in the cabinet and not hooked up. No determination is made.



4.12 Ranges/Ovens/Cooktops

Inspected

4.13 Refrigerator

Inspected

4.14 Range Hood / Downdraft Stovetop Vent

Inspected

4.15 Switches and Fixtures

Inspected


4.16 Outlets (Correct polarity and Grounding) GFI's where needed

Item of Concern

123 N Anystreet Page 25 of 105

All Outlets within 6 feet of the kitchen sink should be GFI protected for safety purposes. Recommend further evaluation and repair by a licensed and qualified professional.





Daisy chain GFI

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 26 of 105

5. Laundry Room/ Area/ Closet

The home inspector shall observe and operate the basic functions of the following kitchen appliances: Permanently installed dishwasher, through its normal cycle; Range, cook top, and permanently installed oven; Trash compactor; Garbage disposal; Ventilation equipment or range hood; and Permanently installed microwave oven. The home inspector is not required to observe: Clocks, timers, self-cleaning oven function, or thermostats for calibration or automatic operation; Non built-in appliances; or Refrigeration units. The home inspector is not required to operate: Appliances in use; or Any appliance that is shut down or otherwise inoperable.

Styles & Materials

Floor: Dryer Power Source: Dryer Vent Material:

Carpet 220 Electric Flexible Metal

Dryer Vent Location: Washing Machine Supply Lines:
Wall Not Present (Recommend Stainless Steel)

Items

5.0 Ceiling

Inspected

5.1 Walls

Inspected

5.2 Floors

Inspected

5.3 Doors

Inspected, Maintenance / Monitor Recommended

The laundry room door will not shut due to shifting and settling. Recommend repair.



5.4 Windows

Not Present

5.5 Laundry Room Vented

Not Present

5.6 Plumbing Water Supply, Distribution System and Fixtures

Inspected

5.7 Washer Drain Line

Inspected

5.8 Electrical Outlets, Switches and Fixtures

Inspected

Inland Northwest Home Inspection LLC

Customer

5.9 Clothes Dryer Vent Piping (Visible Portion)

Inspected

The built-in appliances of the home were inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 28 of 105

6(A) . Master Bath

Styles & Materials

Floor: Bathroom Window(s): Exhaust Fans:

Tile (Ceramic, Porcelain) Yes None

Tubs/ Shower pans: Shower/ Tub Enclosures- Surrounds: Bathroom Heat source:

Tile/ stone Shower Pan Tile (Porcelain, Ceramic, Glass, Other) None Visible

Whirlpool Tub

Items

6.0.A Ceiling

Item of Concern

Visible moisture damage on the ceiling due to lack of ventilation. Recommend further evaluation and repair.



6.1.A Walls

Inspected

6.2.A Floors

Inspected

6.3.A Doors

Inspected

6.4.A Windows

Inspected

6.5.A Counters and Cabinets (representative number)

Inspected

6.6.A Sinks

Inspected

6.7.A Plumbing: Drain, Waste and Vent Systems

Inspected

6.8.A Plumbing: Water Supply lines, Valves, Faucets

Inspected

6.9.A Toilets:Bowls, Tanks, Lids

Item of Concern

Toilet bowl is loose from the floor. Recommend tightening. Use caution when tightening so as not to crack the bowl.



6.10.A Toilets: Supply line, Shut-off valve and Flush and Fill Valve

Inspected

6.11.A Tubs & Shower pans

Inspected

6.12.A Tub and Shower Controls and Shower heads

Inspected, Maintenance / Monitor Recommended

Tub control escutcheon does not attach to valve stem properly. Recommend repair by a licensed plumber.



6.13.A Tub and Shower enclosures

Inspected

6.14.A Outlets, Switches and Fixtures

Inspected

6.15.A Caulking (Around sinks, Toilets, Tubs/ Showers/Surronds, Backsplashes)

Inspected

6.16.A Exhaust fan

Not Present

6.17.A Whirlpool Tub (access door present)

Item of Concern

There is no visible access door to the whirlpool tub equipment. Recommend installing access door for servicing purposes.



6.18.A Heat Source Verified

Not Present

123 N Anystreet Page 31 of 105

6(B). Top Floor 3/4 Bath

Styles & Materials

Floor: Bathroom Window(s): Exhaust Fans:

Linoleum/Vinyl Yes None

Tubs/ Shower pans: Shower/ Tub Enclosures- Surrounds: Bathroom Heat source:

Fiberglass Shower Pan Fiberglass None Visible

Items

6.0.B Ceiling

Inspected

6.1.B Walls

Inspected

6.2.B Floors

Inspected

6.3.B Doors

Inspected, Maintenance / Monitor Recommended Damaged bathroom door needs replacing.



6.4.B Windows

Inspected

6.5.B Counters and Cabinets (representative number)

Inspected

6.6.B Sinks

Inspected

6.7.B Plumbing: Drain, Waste and Vent Systems

Inspected

6.8.B Plumbing: Water Supply lines, Valves, Faucets

Inspected

6.9.B Toilets:Bowls, Tanks, Lids

Inspected

6.10.B Toilets: Supply line, Shut-off valve and Flush and Fill Valve

Maintenance / Monitor Recommended

The toilet valve in the 3/4 bath bleeds off and causes the toilet to refill on an approximate 10 minute cycle. Recommend replacing valve.



6.11.B Tubs & Shower pans

Inspected, Item of Concern

The drain grate is missing from the shower in the 3/4 bath. Recommend installing new grate to prevent objects from entering drain line.



6.12.B Tub and Shower Controls and Shower heads

Inspected

6.13.B Tub and Shower enclosures

Inspected


6.14.B Outlets, Switches and Fixtures

Item of Concern

123 N Anystreet Page 33 of 105

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.





GFI protection

6.15.B Caulking (Around sinks, Toilets, Tubs/ Showers/Surronds, Backsplashes)

Not Present

6.16.B Exhaust fan

Not Present

6.17.B Heat Source Verified

Not Present

123 N Anystreet Page 34 of 105

6(C). Main Floor Full Bath

Styles & Materials

Floor: Bathroom Window(s): Exhaust Fans:

Linoleum/Vinyl Yes Fan only

Tubs/ Shower pans: Shower/ Tub Enclosures- Surrounds: Bathroom Heat source:

Steel/ Cast Iron Tub Plastic- Marlite- Mylar None Visible

Items

6.0.C Ceiling

Inspected

6.1.C Walls

Inspected

6.2.C Floors

Inspected

6.3.C Doors

Inspected

6.4.C Windows

Inspected

6.5.C Counters and Cabinets (representative number)

Inspected

6.6.C Sinks

Inspected

6.7.C Plumbing: Drain, Waste and Vent Systems

Inspected

6.8.C Plumbing: Water Supply lines, Valves, Faucets

Inspected

6.9.C Toilets:Bowls, Tanks, Lids

Inspected

6.10.C Toilets: Supply line, Shut-off valve and Flush and Fill Valve

Inspected

6.11.C Tubs & Shower pans

Inspected

6.12.C Tub and Shower Controls and Shower heads

Maintenance / Monitor Recommended

Shower diverter valve does not operate properly. Recommend repair.



6.13.C Tub and Shower enclosures


Inspected

6.14.C Outlets, Switches and Fixtures

Item of Concern

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.





GFI protection

6.15.C Caulking (Around sinks, Toilets, Tubs/ Showers/Surronds, Backsplashes)

Inspected

6.16.C Exhaust fan

Inspected

6.17.C Heat Source Verified

Not Present

123 N Anystreet Page 36 of 105

6(D) . 1/2 Bath

Styles & Materials

Floor:

Linoleum/Vinyl

Bathroom Window(s):No

Exhaust Fans:

Fan only

Bathroom Heat source:

None Visible

Items

6.0.D Bathroom See Comment Below

Additional Information

The half bath on the main floor is under construction at the time of the inspection. Half bath was not inspected. No determination is made it to the components.



6.1.D Ceiling

Inspected

6.2.D Walls

Item of Concern

Damaged walls needing repair.



123 N Anystreet Page 37 of 105

6.3.D Floors

Inspected

6.4.D Doors

Inspected

6.5.D Windows

Not Present

6.6.D Counters and Cabinets (representative number)

Not Present

6.7.D Sinks

Not Inspected

Wall hung sink was not inspected no determination is made.



6.8.D Plumbing: Drain, Waste and Vent Systems

Not Inspected

6.9.D Plumbing: Water Supply lines, Valves, Faucets

Not Inspected

6.10.D Toilets:Bowls, Tanks, Lids

Not Present

6.11.D Toilets: Supply line, Shut-off valve and Flush and Fill Valve


Not Present

6.12.D Outlets, Switches and Fixtures

Item of Concern

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.





GFI protection

6.13.D Caulking (Around sinks, Toilets, Tubs/ Showers/Surronds, Backsplashes)

Not Present

6.14.D Exhaust fan

Item of Concern

The fan did not operate at the time of the inspection. Recommend repair.



123 N Anystreet Page 39 of 105

Inland Northwest Home Inspection LLC

Customer

6.15.D Heat Source Verified

Not Present

123 N Anystreet Page 40 of 105

7. Rooms

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

Styles & Materials

Floor Covering(s):

Area rug Carpet Unfinished Sloping Uneven Squeaking

Interior Doors:

Window Types: Hollow core Single-hung

Sliders Fixed Glass (non opening)

Items

7.0 Ceilings

Maintenance / Monitor Recommended

Damaged ceilings throughout the house with possible organic growth indicating a moisture related problem.(ie: lack of ventilation, possible leak) Recommend further evaluation for needed repairs.



7.1 Walls

Maintenance / Monitor Recommended

123 N Anystreet Page 41 of 105 Multiple areas of damaged walls throughout the house. Recommend repair as needed.





7.2 Floors

Inspected

7.3 Doors (representative number)

Inspected

7.4 Window Operation (representative number)

Inspected

7.5 Outlets, Switches and Fixtures

Inspected

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 42 of 105

Fireplace Type:Woodburning Stove

8. Interior Components

The home inspector shall observe: Walls, ceiling, and floors; Steps, stairways, balconies, and railings; Counters and a representative number of installed cabinets; and A representative number of doors and windows. The home inspector shall: Operate a representative number of windows and interior doors; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to observe: Paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors; Carpeting; or Draperies, blinds, or other window treatments.

Styles & Materials

Window Structure / Storm windows not inspected:

Single pane wood frame

Double pane

Metal

Vinyl

Fireplace Location(s):

Living Room Kitchen/ Dining Ceiling Fan Locations:

Living Room Master Bedroom

Fireplace(s):

Two

Items

8.0 Steps, Stairways, Balconies and Railings

Inspected

8.1 Windows Stucture & Stability (Material and seals)

Inspected

8.2 Ceiling Fans

Inspected

8.3 Fireplaces/ Hearths/ Mantels (Inspect Fireboxes and Dampers, Flues)

Inspected

8.4 Woodburning /Pellet Stoves (Doors, Door Gaskets, Dampers, Fireplace Surrounds)

Inspected, Not Inspected, Item of Concern

123 N Anystreet

(1) The wood burning stove in the living room was not completely installed up at the time of the inspection. No determination is made.



123 N Anystreet Page 44 of 105

(2) A non flammable surface should extend a minimum of 18 in from the front of the stove for safety purposes.



(3) There is a minimum clearance requirement between single wall stove pipes and flammable surfaces. Recommend consulting with a license HVAC contractor to insure proper clearance is met.





123 N Anystreet Page 45 of 105

8.5 Fireplace Blowers

Not Inspected

8.6 Smoke Detectors

Inspected, Item of Concern

There are several smoke detectors mounted throughout the house.

Recommend installing smoke detectors throughout the house. One in each bedroom and in the common hallway is recommended.

Smoke detector batteries should be changed twice annually, typically this is done when the clocks move forward and back




8.7 CO (Carbon Monoxide) Detectors

Inspected, Item of Concern

There was one visible carbon monoxide detector at the top of the stairs.

CO (Carbon Monoxide) detectors are recommended in all homes for safety purposes. There should be a CO detector on each floor (when applicable) and located in hallways outside of bedrooms..





CO detector

The interior of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection did not involve moving furniture and inspecting behind furniture, area rugs or areas obstructed from view. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 46 of 105

9. Attic/ Roof System (Interior)

The home inspector shall observe: Roof covering; Roof drainage systems; Flashings; Skylights, chimneys, and roof penetrations; and Signs of leaks or abnormal condensation on building components. The home inspector shall: Describe the type of roof covering materials; and Report the methods used to observe the roofing. The home inspector is not required to: Walk on the roofing; or Observe attached accessories including but not limited to solar systems, antennae, and lightning arrestors.

Styles & Materials

Attic info:

Door

Located in/at

Hallway

Storage

No visible access to a portion of the attic

Top floor common room

Ventilation:

None found

Method used to observe attic:

From entry

Limited accessibility due to obstacles

Limited access to part of attic

Roof Structure:

2 X 4 Rafters Plywood Sheathing

Planking

Attic Insulation:

Visible from access point Batt **Fiberglass** R-19

Bathroom Exhaust Fans:

Not present

Kitchen Exhaust Venting:

Not present

Items

9.0 Attic See Comments Below

Additional Information

Sections of attic were both finished as well as unfinished. Limited visibility in attic sections due to personal belongings being stored. Inspection refers to visible areas only. Sections of the attic were not accessible.



Page 47 of 105 123 N Anystreet





9.1 Accessibility of Attic Access

Inspected, Limited Visibility

9.2 Roof Structure and Attic (Structural integrity of trusses, rafters and components)Inspected

9.3 Roof Structure (Moisture/ Condensation and related issues)
Inspected

9.4 Ventilation of Roof/Attic (Visual from Attic)

Not Present

9.5 Skylights, Chimneys and Roof Penetrations (Visual from Attic)
Not Present

9.6 Soffit baffles installed and functional

Not Present

9.7 Ventilation Fans and Thermostatic Controls in Attic

Not Present

9.8 Bathroom Exhaust Venting

Not Present, Limited Visibility

123 N Anystreet Page 48 of 105

Inland Northwest Home Inspection LLC

Customer

9.9 Kitchen Exhaust Venting

Not Present

9.10 Insulation in Attic

Inspected

9.11 Visible Electric Wiring in Attic

Inspected

The roof of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Roof coverings and skylights can appear to be leak proof during inspection and weather conditions. Our inspection makes an attempt to find a leak but sometimes cannot. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 49 of 105

10. Crawlspace

The Home Inspector shall observe structural components including foundations, floors, walls, columns or piers, ceilings and roof. The home inspector shall describe the type of Foundation, floor structure, wall structure, columns or piers, ceiling structure, roof structure. The home inspector shall: Probe structural components where deterioration is suspected; Enter under floor crawl spaces, basements, and attic spaces except when access is obstructed, when entry could damage the property, or when dangerous or adverse situations are suspected; Report the methods used to observe under floor crawl spaces and attics; and Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components. The home inspector is not required to: Enter any area or perform any procedure that may damage the property or its components or be dangerous to or adversely effect the health of the home inspector or other persons.

Styles & Materials

Crawlspace type: Crawlspace Access: Method used to observe Crawlspace:

Full Crawlspace Exterior Hatch Crawled
Pests

Debris Obstructed

Foundation Walls: Crawlspace Floor: Columns or Piers:

Masonry block Dirt Cocrete/ Masonry piers
Dry stacked rock or stone

Wood piers Wood columns Wood beams

Sub Floor Structure: Crawlspace Insulation: Vapor Barrier:

2 X 10 Between Floor Joists Plastic

Wood joists Batts No Vapor Barrier Present Planking

Items

Wood beams

10.0 Foundation Walls- Structural (Report visible large cracks or signs of active movment)
Inspected

10.1 Foundation Walls- Moisture penetration (Report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components.)

Inspected

10.2 Piers/ Columns / Beams & Girders / Pony walls

Item of Concern

123 N Anystreet Page 50 of 105

Evidence of a wood destroying organism and failed beam due to the a wood destroying organism. Recommend further evaluation by license pest inspector and further evaluation by a licensed contractor for all needed repairs in the crawlspace.



10.3 Floors (Visible floor of crawlspace)

Item of Concern

Leftover debris and wood in crawlspace should be cleaned out to prevent possible WDO's





10.4 Seismic Bolts

Not Present

10.5 Drainage (Report Evidence of Moisture Damage or Standing water)

Inspected

10.6 Floor Joist (Report broken, deteriorating, sagging or improperly altered floor joists)

Item of Concern

Multiple floor joists have been improperly repaired and modified. Recommend further evaluation by a licensed contractor for needed needed repairs throughout the crawlspace and proceed as recommended.



10.7 Subfloor (Indication of moisture stains/ rotting around shower stalls, tubs and toilets) Limited Visibility

10.8 Insulation Under Floor System

Item of Concern

Insulation is falling down in multiple areas in his being used as nesting material. Recommend further evaluation of entire crawlspace for all needed repairs.



10.9 Vapor Barriers (in Crawlspace)

Item of Concern

123 N Anystreet Page 52 of 105

Inland Northwest Home Inspection LLC

Customer

The vapor barrier is missing throughout the crawlspace and there is visible moisture in areas of the crawlspace. Recommend installing vapor barrier throughout the entire crawlspace to prevent moisture related problems.



10.10 Ventilation of Foundation Areas

Not Present, Limited Visibility

10.11 Visible Electrical Wiring

Limited Visibility

The structure of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 53 of 105

11. Plumbing System

The home inspector shall observe: Interior water supply and distribution system, including: piping materials, supports, and insulation; fixtures and faucets; functional flow; leaks; and cross connections; Interior drain, waste, and vent system, including: traps; drain, waste, and vent piping; piping supports and pipe insulation; leaks; and functional drainage; Hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, flues, and vents; Fuel storage and distribution systems including: interior fuel storage equipment, supply piping, venting, and supports; leaks; and Sump pumps. The home inspector shall describe: Water supply and distribution piping materials; Drain, waste, and vent piping materials; Water heating equipment; and Location of main water supply shutoff device. The home inspector shall operate all plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance. The home inspector is not required to: State the effectiveness of anti-siphon devices; Determine whether water supply and waste disposal systems are public or private; Operate automatic safety controls; Operate any valve except water closet flush valves, fixture faucets, and hose faucets; Observe: Water conditioning systems; Fire and lawn sprinkler systems; On-site water supply quantity and quality; On-site waste disposal systems; Foundation irrigation systems; Spas, except as to functional flow and functional drainage; Swimming pools; Solar water heating equipment; or Observe the system for proper sizing, design, or use of proper materials.

Styles & Materials

Water Source:

Public

Plumbing Water Supply (into home):

Not visible

Main Water Shutoff Location:

Crawlspace

Pressure Reducer:

Not Visible

Main Fuel Shut-Off Location:

East side of house

Plumbing Water Distribution (Visible/Inside Home):

Water Heater Power Source:

Galvanized Copper PEX

Electric

Limited Visibiity

Plumbing Waste/ Drain line (**Visible Drain Lines):**

Cast iron

ABS

Water Heater Capacity:

(2)40 Gallon 50-52 Gallon

WaterTemperature Tested:

Between 115-120 Degrees

Water Heater Location:

Bathroom Closet

RHEEM

WH Manufacturer:

Fuel line: Black Iron

Water Heater Approx. Age:

6-8 Years

<u>Items</u>

11.0 Main Water Shut-off Device

Limited Visibility


11.1 Plumbing Water Supply, Distribution System and Fixtures

Inspected, Limited Visibility

11.2 Plumbing Drain, Waste and Vent Systems

Inspected, Limited Visibility, Item of Concern

123 N Anystreet Page 54 of 105 Due to the age of the home recommendation is to have main sewer line scoped to determine material and stability of the line.



11.3 Hot Water Systems, Controls, Chimneys, Flues and Vents Inspected

123 N Anystreet Page 55 of 105

(1) Water heater data plate located in bathroom


Serial No.	M401406423 XE40M06ST45U0		_
Model No			
Manufacture Date.	020CT2014		
Cap. U.S. Gals.	40	13	
Phase	1 1	13	
Volts AC	240	208	
Upper Element Watts	4500	3380	
Lower Element Watts	4500	3380	
Total Watts	4500	3380	
Sees Sees Sompany, Inc. Sees sees a Sees Sees USA			

(2) Drip pans have been required below water heaters since 2012. Recommend installing drip pan. Water heater in bathroom.



123 N Anystreet Page 56 of 105

(3) Water heater data plate: upstairs closet.



11.4 TPR Valve and Extension (Temp., Pressure Relief)

Item of Concern


The TPR valve extension is missing or too short. Code requires that the extension extends to no more than 6 inches above the floor. The desired location is for the line to extend to a floor drain if accessible or to the exterior of the home.

Both water heaters.



123 N Anystreet Page 57 of 105





T & P options

11.5 Fuel Storage and Distribution Systems (Interior fuel storage, piping, venting, supports, leaks)

Not Inspected

11.6 Sump Pump

Not Present

11.7 Main Fuel Shut-off

Inspected

123 N Anystreet Page 58 of 105

The plumbing in the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Washing machine drain line for example cannot be checked for leaks or the ability to handle the volume during drain cycle. Older homes with galvanized supply lines or cast iron drain lines can be obstructed and barely working during an inspection but then fails under heavy use. If the water is turned off or not used for periods of time (like a vacant home waiting for closing) rust or deposits within the pipes can further clog the piping system. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 59 of 105

12. Electrical System

The home inspector shall observe: Service entrance conductors; Service equipment, grounding equipment, main over current device, and main and distribution panels; Amperage and voltage ratings of the service; Branch circuit conductors, their over current devices, and the compatibility of their ampacities and voltages; The operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles located inside the house, garage, and on the dwelling's exterior walls; The polarity and grounding of all receptacles within six feet of interior plumbing fixtures, and all receptacles in the garage or carport, and on the exterior of inspected structures; The operation of ground fault circuit interrupters; and Smoke detectors. The home inspector shall describe: Service amperage and voltage; Service entry conductor materials; Service type as being overhead or underground; and Location of main and distribution panels. The home inspector shall report any observed aluminum branch circuit wiring. The home inspector shall report on presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system. The home inspector is not required to: Insert any tool, probe, or testing device inside the panels; Test or operate any over current device except ground fault circuit interrupters; Dismantle any electrical device or control other than to remove the covers of the main and auxiliary distribution panels; or Observe: Low voltage systems; Security system devices, heat detectors, or carbon monoxide detectors; Telephone, security, cable TV, intercoms, or other ancillary wiring that is not a part of the primary electrical distribution system; or Built-in vacuum equipment.

Styles & Materials

Electrical Service Conductors:

Overhead service Aluminum 220 volts

Panel Type:

Split Buss Panel

Wiring Methods:

Romex Cloth Wrapped **Main Electrical Panel**

Location: Interior Wall

Electric Panel Manufacturer:

ZINSCO/ SYLVANIA

Panel Capacity:

200 AMP Adequate

Branch wire 15 and 20

AMP:

Solid core copper

Items

12.0 Service Entrance Conductors

Inspected

12.1 Service and Grounding Equipment, Main Breaker(s), Main Service Panel(s)

Inspected

12.2 Electrical Sub-panels and overload protection devices. Report on compatibility of breaker to wire size and isolated ground and neutral wires.

Inspected

12.3 Branch Circuit Conductors, Overcurrent Devices and their Compatibility

Item of Concern

Inland Northwest Home Inspection LLC

Customer

Sylvania/ Zinsco electrical panels are obsolete and a potential safety hazard. Recommend further evaluation by a licensed electrician and proceed as recommended.

For further information go to: http://www.ismypanelsafe.com/zinsco.php

123 N Anystreet Page 61 of 105



123 N Anystreet Page 62 of 105

Inland Northwest Home Inspection LLC

Customer

12.4 Connected Devices and Fixtures (Observed from a representative number operation of, lighting fixtures, switches and receptacles located inside the house)

Inspected

12.5 Operation of GFCI (Ground Fault Circuit Interrupters) Breakers

Not Present

12.6 Operation of AFCI (ARC Fault Circuit Interrupters) Breakers

Not Present

The electrical system of the home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. Outlets were not removed and the inspection was only visual. Any outlet not accessible (behind the refrigerator for example) was not inspected or accessible. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 63 of 105

13. Heating System(s)

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

Styles & Materials

Heat Type:

Electric Baseboard Heaters Electric Wall Heaters Gas Wall Heater

Number of Heating Systems (central systems only):

One

Filter Location:

N/A

Aux. - Emergency Heat for Heat pump system:

None

Furnace- Heating System Approximate Age:

31+ Years

Energy Source:

Gas-Natural/ Propane Electric

Visible Ductwork:

N/A

Items

13.0 Heating Equipment

Inspected, Item of Concern

123 N Anystreet Page 64 of 105

The gas wall heater did not operate at the time of the inspection. Recommend further evaluation by licensed HVAC technician.



13.1 Normal Operating Controls (Thermostats)

Inspected

13.2 Distribution Systems (including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units and convectors)

Not Present

13.3 Presence of Installed Heat Source in Each Room

Not Present

13.4 Chimneys, Flues and Vents for heat systems other than solid fuel

Limited Visibility

13.5 Combustion air intake (Sufficient air for proper operation)

Inspected

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 65 of 105

A/C Condenser Approx.

14. A/C System(s)

The home inspector shall observe permanently installed heating and cooling systems including: Heating equipment; Cooling Equipment that is central to home; Normal operating controls; Automatic safety controls; Chimneys, flues, and vents, where readily visible; Solid fuel heating devices; Heat distribution systems including fans, pumps, ducts and piping, with supports, insulation, air filters, registers, radiators, fan coil units, convectors; and the presence of an installed heat source in each room. The home inspector shall describe: Energy source; and Heating equipment and distribution type. The home inspector shall operate the systems using normal operating controls. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance. The home inspector is not required to: Operate heating systems when weather conditions or other circumstances may cause equipment damage; Operate automatic safety controls; Ignite or extinguish solid fuel fires; or Observe: The interior of flues; Fireplace insert flue connections; Humidifiers; Electronic air filters; or The uniformity or adequacy of heat supply to the various rooms.

Styles & Materials

Cooling Equipment Type: **Cooling Equipment Energy**

Window / Wall AC (Not Source: Age: Inspected)

Electricity N/A

Items

The heating and cooling system of this home was inspected and reported on with the above information. While the inspector makes every effort to find all areas of concern, some areas can go unnoticed. The inspection is not meant to be technically exhaustive. The inspection does not involve removal and inspection behind service door or dismantling that would otherwise reveal something only a licensed heat contractor would discover. Please be aware that the inspector has your best interest in mind. Any repair items mentioned in this report should be considered before purchase. It is recommended that qualified contractors be used in your further inspection or repair issues as it relates to the comments in this inspection report.

123 N Anystreet Page 66 of 105

SUMMARY 1 (Items of Concern and Potential Safety Issues)



P.O.Box 703 Lewiston Idaho 83501 208.791.5933

> **Customer** Inhi Customer

Address 123 N Anystreet Any Town ID 99999

The following items or discoveries indicate that these systems or components **do not function as intended** or **adversely affects the habitability of the dwelling;** or **warrants further investigation by a specialist,** or **requires subsequent observation.** This summary shall not contain recommendations for routine upkeep of a system or component to keep it in proper functioning condition or recommendations to upgrade or enhance the function or efficiency of the home. This Summary is not the entire report. The complete report may include additional information of concern to the customer. It is recommended that the customer read the complete report.

1. Grounds

1.0 Sidewalks/ Service Walks

Item of Concern

The sidewalk on the back of the house has settled creating a negative grade towards the house. This is allowing water to flow towards house and entering the crawlspace. Recommend further evaluation by licensed contractor to correct grade and proceed as recommended.

123 N Anystreet Page 67 of 105



1.1 Steps/ Stoops/ Ramps and Applicable Railings


Item of Concern

(1) The wood steps to the front door show signs of wood rot and deterioration, as well as loose planking. This is creating a potential safety hazard. Recommend rebuilding steps for safety purposes.


123 N Anystreet Page 68 of 105



(2) Back steps to upper deck are failing and are a safety hazard. Recommend rebuilding steps properly prior to use.



123 N Anystreet Page 69 of 105



1.2 Patios and Applicable Railings

Inspected, Item of Concern

Deteriorating brick and sand patios creating multiple trip hazards. Recommend repair as needed.



1.3 Decks, Porches, Balconies and Applicable Railings

Item of Concern

Both upper and lower decks are not properly attached to the house. Deck ledgers should be attached with 1/2 lag bolts on 2 ft centers. Further evaluation for needed repairs by a licensed contractor is recommended.

123 N Anystreet Page 70 of 105



2. Exterior

2.0 Roof Drainage Systems (Gutters/Downspouts)

Item of Concern

Recommend installing gutters with proper downspouts around the entire house in order to prevent unwanted moisture from entering crawlspace.




2.10 Exterior Outlets (Correct polarity & Grounding -GFI protected- Weatherproof covers) Item of Concern

(1) All exterior outlets should be GFI protected for safety purposes. Recommend installing GFI protection for exterior outlets. (Either GFI outlets or breaker)

123 N Anystreet Page 71 of 105






GFI Breaker/ outlet

(2) All electrical wiring should be installed in a junction box of proper cover for safety purposes.

123 N Anystreet Page 72 of 105



3. Roof System (Exterior)

3.0 Roof Coverings

Inspected, Item of Concern, Maintenance / Monitor Recommended, Deffered cost item (1) Improperly lapped shingles on roof. Recommend further evaluation by license roofer for all needed repairs.

123 N Anystreet Page 73 of 105



(3) Broken and missing shingles, excessive granule loss and cracking are all indications that the roof is nearing the end of its typical lifespan. Repairs may be needed within the next 5 years.



123 N Anystreet Page 74 of 105





3.1 Flashings (Roof Edge & Wall & Counter Flashing)

Item of Concern

The drip edge is separating from the fascia in multiple sections of the roof. The drip edge prevents water from wicking up the sheathing creating wood rot and possible mold related issues. Recommend further evaluation by a licensed roofer for all needed repairs and proceed as recommended



3.3 Plumbing Vent Flashings Item of Concern

123 N Anystreet Page 75 of 105

Two plumbing vent flashing Have failed and require replacing. Recommend repair by a qualified professional





3.5 Class B Vents (Stove Pipes) / Furnace Exhaust Vents (PVC) & Flashings Item of Concern

Rain cap /spark arrestor is missing from stove pipe. Recommend repair for safety purposes.



123 N Anystreet Page 76 of 105

4. Kitchen Components and Appliances

4.9 Dishwasher

Not Inspected, Item of Concern

The dishwasher did not operate at the time of the inspection. No determination is made.



4.11 Food Waste Disposer

Item of Concern

The garbage disposal was sitting in the cabinet and not hooked up. No determination is made.

123 N Anystreet Page 77 of 105




4.16 Outlets (Correct polarity and Grounding) GFI's where needed

Item of Concern

All Outlets within 6 feet of the kitchen sink should be GFI protected for safety purposes. Recommend further evaluation and repair by a licensed and qualified professional.





Daisy chain GFI

123 N Anystreet Page 78 of 105

6(A) . Master Bath

6.0.A Ceiling

Item of Concern

Visible moisture damage on the ceiling due to lack of ventilation. Recommend further evaluation and repair.



6.17.A Whirlpool Tub (access door present)

Item of Concern

There is no visible access door to the whirlpool tub equipment. Recommend installing access door for servicing purposes.



6(B) . Top Floor 3/4 Bath

6.11.B Tubs & Shower pans

Inspected, Item of Concern

The drain grate is missing from the shower in the 3/4 bath. Recommend installing new grate to prevent objects from entering drain line.

123 N Anystreet Page 79 of 105




6.14.B Outlets, Switches and Fixtures

Item of Concern

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.





GFI protection

6(C) . Main Floor Full Bath


6.14.C Outlets, Switches and Fixtures

Item of Concern

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.

123 N Anystreet Page 80 of 105





GFI protection

6(D) . 1/2 Bath

6.2.D Walls

Item of Concern

Damaged walls needing repair.




6.12.D Outlets, Switches and Fixtures

Item of Concern

GFI protected outlets are recommended in all bathrooms for safety purposes. Recommend repair by a qualified professional.

123 N Anystreet Page 81 of 105





GFI protection

6.14.D Exhaust fan

Item of Concern

The fan did not operate at the time of the inspection. Recommend repair.



8. Interior Components

8.4 Woodburning /Pellet Stoves (Doors, Door Gaskets, Dampers, Fireplace Surrounds)

123 N Anystreet Page 82 of 105

Customer

Inspected, Not Inspected, Item of Concern

(2) A non flammable surface should extend a minimum of 18 in from the front of the stove for safety purposes.



(3) There is a minimum clearance requirement between single wall stove pipes and flammable surfaces. Recommend consulting with a license HVAC contractor to insure proper clearance is met.

123 N Anystreet Page 83 of 105





8.6 Smoke Detectors

Inspected, Item of Concern

There are several smoke detectors mounted throughout the house.

Recommend installing smoke detectors throughout the house. One in each bedroom and in the common hallway is recommended.

Smoke detector batteries should be changed twice annually, typically this is done when the clocks move forward and back

123 N Anystreet Page 84 of 105




8.7 CO (Carbon Monoxide) Detectors

Inspected, Item of Concern

There was one visible carbon monoxide detector at the top of the stairs.

CO (Carbon Monoxide) detectors are recommended in all homes for safety purposes. There should be a CO detector on each floor (when applicable) and located in hallways outside of bedrooms..





CO detector

10. Crawlspace

10.2 Piers/ Columns / Beams & Girders / Pony walls

Item of Concern

Evidence of a wood destroying organism and failed beam due to the a wood destroying organism. Recommend further evaluation by license pest inspector and further evaluation by a licensed contractor for all needed repairs in the crawlspace.

123 N Anystreet Page 85 of 105



10.3 Floors (Visible floor of crawlspace)

Item of Concern

Leftover debris and wood in crawlspace should be cleaned out to prevent possible WDO's





10.6 Floor Joist (Report broken, deteriorating, sagging or improperly altered floor joists) Item of Concern

Multiple floor joists have been improperly repaired and modified. Recommend further evaluation by a licensed contractor for needed needed repairs throughout the crawlspace and proceed as recommended.

123 N Anystreet Page 86 of 105



10.8 Insulation Under Floor System

Item of Concern

Insulation is falling down in multiple areas in his being used as nesting material. Recommend further evaluation of entire crawlspace for all needed repairs.



10.9 Vapor Barriers (in Crawlspace)

Item of Concern

The vapor barrier is missing throughout the crawlspace and there is visible moisture in areas of the crawlspace. Recommend installing vapor barrier throughout the entire crawlspace to prevent moisture related problems.

123 N Anystreet Page 87 of 105




11. Plumbing System

11.2 Plumbing Drain, Waste and Vent Systems

Inspected, Limited Visibility, Item of Concern

Due to the age of the home recommendation is to have main sewer line scoped to determine material and stability of the line.

123 N Anystreet Page 88 of 105



11.3 Hot Water Systems, Controls, Chimneys, Flues and Vents Inspected

(2) Drip pans have been required below water heaters since 2012. Recommend installing drip pan.

Water heater in bathroom.

123 N Anystreet Page 89 of 105



11.4 TPR Valve and Extension (Temp., Pressure Relief)

Item of Concern


The TPR valve extension is missing or too short. Code requires that the extension extends to no more than 6 inches above the floor. The desired location is for the line to extend to a floor drain if accessible or to the exterior of the home.

Both water heaters.



123 N Anystreet Page 90 of 105





T & P options

12. Electrical System

12.3 Branch Circuit Conductors, Overcurrent Devices and their Compatibility Item of Concern

Sylvania/ Zinsco electrical panels are obsolete and a potential safety hazard. Recommend further evaluation by a licensed electrician and proceed as recommended.

123 N Anystreet Page 91 of 105

For further information go to: http://www.ismypanelsafe.com/zinsco.php

123 N Anystreet Page 92 of 105



123 N Anystreet Page 93 of 105

13. Heating System(s)

13.0 Heating Equipment

Inspected, Item of Concern

The gas wall heater did not operate at the time of the inspection. Recommend further evaluation by licensed HVAC technician.



Home inspectors are not required to report on the following: Life expectancy of any component or system; The causes of the need for a repair; The methods, materials, and costs of corrections; The suitability of the property for any specialized use; Compliance or non-compliance with codes, ordinances, statutes, regulatory requirements or restrictions; The market value of the property or its marketability; The advisability or inadvisability of purchase of the property; Any component or system that was not observed; The presence or absence of pests such as wood damaging organisms, rodents, or insects; or Cosmetic items, underground items, or items not permanently installed. Home inspectors are not required to: Offer warranties or guarantees of any kind; Calculate the strength, adequacy, or efficiency of any system or component; Enter any area or perform any procedure that may damage the property or its components or be dangerous to the home inspector or other persons; Operate any system or component that is shut down or otherwise inoperable; Operate any system or component that does not respond to normal operating controls; Disturb insulation, move personal items, panels, furniture, equipment, plant life, soil, snow, ice, or debris that obstructs access or visibility; Determine the presence or absence of any suspected adverse environmental condition or hazardous substance, including but not limited to mold, toxins, carcinogens, noise, contaminants in the building or in soil, water, and air; Determine the effectiveness of any system installed to control or remove suspected hazardous substances; Predict future condition, including but not limited to failure of components; Since this report is provided for the specific benefit of the customer(s), secondary readers of this information should hire a licensed inspector to perform an inspection to meet their specific needs and to obtain current information concerning this property.

123 N Anystreet Page 94 of 105

Inland Northwest Home Inspection LLC

Customer

 $\textit{Prepared Using HomeGauge} \ \underline{\textit{http://www.HomeGauge.com}}: Licensed \ To \ Chip \ Kenny$

123 N Anystreet Page 95 of 105

SUMMARY 2 (Maintenance/ Monitor Items/ Deferred Cost Items)



Inland Northwest Home Inspection LLC

P.O.Box 703 Lewiston Idaho 83501 208.791.5933

> **Customer** Inhi Customer

Address

123 N Anystreet Any Town ID 99999

The Items in this summary are showing signs of aging or typical age related issues. Items in this summary will be noted individually if maintenance is needed at this time or if monitoring for future maintenance is recommended. Typically items in this category do not require a licensed or certified repair person or contractor. Items listed here can be performed by the home owner (depending on skill level) or by a qualified handy man.

2. Exterior

2.1 Siding


Inspected, Maintenance/ Montitoring Recommended

The siding is an overall satisfactory condition with typical maintenance and minor repairs required. Recommend repair as needed, prep and paint/ stain in order to prevent deterioration of the siding. This type of siding is very susceptible to moisture penetration if not properly maintained.

123 N Anystreet Page 96 of 105

Inland Northwest Home Inspection LLC

Customer



123 N Anystreet Page 97 of 105







2.2 Soffit/ Fascia/ Flashing


Inspected, Maintenance/ Montitoring Recommended

Multiple areas of damaged soffit and fascia. Recommend repair as needed, prep and paint..

123 N Anystreet Page 98 of 105








2.4 Window, Door & Corner Trim

Inspected

Areas of door, window and / or corner trim that shows signs of wood rot and deterioration due to lack of maintenance. Recommend repairing trim as needed, prep and paint to prevent further deterioration.

123 N Anystreet Page 99 of 105





3. Roof System (Exterior)

3.0 Roof Coverings

Inspected, Item of Concern, Maintenance / Monitor Recommended, Deffered cost item
(2) Cleaning moss from the roof is recommended in order to extend the lifespan of the covering, DO NOT PRESSURE WASH as this will damage the shingles. Use a rough surface push broom for best results.



123 N Anystreet Page 100 of 105


4. Kitchen Components and Appliances

4.10 Dishwasher drain line

Maintenance / Monitor Recommended

Dishwasher drain line should either be looped at the high point in cabinet or have an air gap installed to prevent backflow from the sink to the dishwasher.





Dishwasher drain line

5. Laundry Room/ Area/ Closet

5.3 Doors

Inspected, Maintenance / Monitor Recommended

The laundry room door will not shut due to shifting and settling. Recommend repair.




123 N Anystreet Page 101 of 105

6(A) . Master Bath

6.9.A Toilets:Bowls, Tanks, Lids

Item of Concern

Toilet bowl is loose from the floor. Recommend tightening. Use caution when tightening so as not to crack the bowl.



6.12.A Tub and Shower Controls and Shower heads

Inspected, Maintenance / Monitor Recommended

Tub control escutcheon does not attach to valve stem properly. Recommend repair by a licensed plumber.



6(B) . Top Floor 3/4 Bath

6.3.B Doors

Inspected, Maintenance / Monitor Recommended

Damaged bathroom door needs replacing.

123 N Anystreet Page 102 of 105



6.10.B Toilets: Supply line, Shut-off valve and Flush and Fill Valve

Maintenance / Monitor Recommended

The toilet valve in the 3/4 bath bleeds off and causes the toilet to refill on an approximate 10 minute cycle. Recommend replacing valve.



6(C) . Main Floor Full Bath

6.12.CTub and Shower Controls and Shower heads

Maintenance / Monitor Recommended

Shower diverter valve does not operate properly. Recommend repair.



123 N Anystreet Page 103 of 105

7. Rooms

7.0 Ceilings

Maintenance / Monitor Recommended

Damaged ceilings throughout the house with possible organic growth indicating a moisture related problem.(ie: lack of ventilation, possible leak) Recommend further evaluation for needed repairs.



7.1 Walls

Maintenance / Monitor Recommended

Multiple areas of damaged walls throughout the house. Recommend repair as needed.





Prepared Using HomeGauge http://www.HomeGauge.com : Licensed To Chip Kenny

123 N Anystreet Page 104 of 105



INVOICE

Inspection Date: 8/3/2018

Report ID: Sample Report 1

Inland Northwest Home Inspection LLC P.O.Box 703 Lewiston Idaho 83501 208.791.5933

Inspected By: Chip Kenny

Customer Info:	Inspection Property:
Inhi Customer	123 N Anystreet Any Town ID 99999
Customer's Real Estate Professional:	

Inspection Fee:

Service	Price	Amount	Sub-Total
Standard Inspection 1001-3000 sqft	325.00	1	325.00
Total mileage	0.00	60	0.00

Tax \$0.00

Total Price \$325.00

Payment Method: Check Payment Status: Paid

Note:

123 N Anystreet Page 105 of 105